

ACCESSIBILITY DATA

For Individual Buildings On Campus

Building	General Accessibility						Restroom Facilities			
	Entrance ramped on ground level	Automatic entrance doors	Number of accessible floors	Stairs non-skid	Interior ramps available	ELEVATORS P=Passenger; F=Freight; *=Braille labels	Restroom designed for wheelchair	Entrance door width = 32"	Wall accessories below 40"/A	Access to showers and tubs
Academic Support Center	yes	yes	1		no		yes	yes	yes	
Apsaruke	yes	yes	3	yes	yes/F	P*	yes	yes	yes	
Art Annex	yes		1		no		yes	yes	yes	
Cisel Hall	yes	yes	4	yes	yes	P*	yes/B	yes	yes	
College of Business	yes	Sky-Bridge	3		yes	P	yes/F	yes	yes	
College of Education	yes	yes	4	yes	no	P*	yes	yes	yes	
College of Technology	yes	yes	2		yes	P*	yes	yes	yes	
Facilities Services	yes		1				yes	yes	yes	
Family Housing	yes	no	1				yes	yes	yes	yes
Liberal Arts	yes	yes	8	yes	no	P*	yes/C	yes	yes	
Library	yes	yes	3	no	yes/F	P*	yes/D	yes	yes	
McMullen Hall	yes	yes	4	yes	no	P*	yes	yes	yes	
Parking Garage	yes			yes	yes	P*				
Petro Hall	yes	yes	8	no	no	P*	yes/H	yes	yes	no
Physical Education	yes	yes	2	yes	yes	P*	yes	yes	yes	yes
Rimrock Hall	yes	yes	6	no	no	E/G,P*	yes	yes	yes	yes
Science	yes	yes	3	yes	no	P*	yes	no	yes	
Security	yes		1		yes		yes	yes	yes	
Student Union	yes	yes	2	no	no	P*	yes	yes	yes	

A: In most restrooms, the sinks but not the towels are below 40"
 B: Off ramp between new and old building
 C: 1st floor, between Liberal Arts Building and Library/2nd & 5th floor
 Liberal Arts Building
 D: 2nd floor, between Library doors and stairs

E: Stairs to basement
 F: Wheelchair lifts
 G: Freight elevator does not have automatic doors
 H: Lobby area

Evacuation Procedures for Persons with Disabilities

Persons with disabilities need to become familiar with exits, evacuation procedures and rescue assistance areas in each building. Persons needing rescue assistance should ask someone to immediately notify rescue personnel of their location.

Location of Rescue Assistance Areas: It is your responsibility to verify the location of rescue assistance areas upon arrival at MSU Billings.

Apsaruke	East and West corridor ends
Cisel Hall	North stairwell landings
College of Education.....	Center stairwell landings
College of Business.....	Stairwell landings near the elevators
College of Technology, 3803 Central Ave.,	Second floor near B012
Liberal Arts Building.....	South stairwell landings
Library.....	East stairwell landings
McMullen Hall.....	Center stairwell landings
Petro Hall	Center stairwell landings
Rimrock Hall.....	Center stairwell landings
Science Building.....	West stairwell landing

In emergency situations, persons unable to use the stairways to exit a building will wait at the nearest designated rescue assistance locations, if safe to do so, until someone comes to help them evacuate the building. Signs in buildings with stairwells indicate designated rescue assistance areas*. MSU Billings Campus Police or the Billings Fire Department will check designated rescue assistance areas for people who need assistance in the building where an evacuation is in progress. In cases of fire drills, the persons needing assistance will be advised by those conducting the drill that if there had been a fire or other emergency, they would have received the necessary help to leave the building. Under no circumstances should anyone use the elevators, nor should any person who is disabled be carried down the stairways unless by trained personnel during an actual emergency evacuation.

In an emergency, ask to have emergency personnel notified immediately of your location.

KEEP DOORS TO STAIRWELLS CLOSED.

Some MSU Billings fire alarms are also equipped with flashing lights since hard-of-hearing students may not hear the audio emergency alarms. It may be necessary to write a note telling the hard-of-hearing student what the emergency is.

Students who are visually impaired may need to take someone's elbow and be escorted to the nearest emergency exit.

*The term *rescue assistance area* is used to describe an area where a person who is unable to evacuate may wait to be rescued. It is not meant to imply compliance to ADAAG standards for new buildings. Persons should ask someone to immediately notify rescue personnel of their location.